

CVFPB Meeting October 24, 2014

USACE INSPECTION RESULTS


Kimberlee Leonard



US Army Corps of Engineers
BUILDING STRONG®



RD 1600, 827, 785, and 537- Sac Yolo North



Map Legend

Project Levees: NLD SYSTEMS and SEGMENTS
(Levee Inspection System Code)

SYSTEM 941

- RD 0537-Lovdal - Unit 1, north of Bypass (LOVN)
- RD 0785-Driver - Unit 1, Sacramento River (DRV1)
- RD 0785-Driver - Unit 2, Yolo Bypass (DRV2)
- RD 0827-Elkhorn - Unit 1, Sacramento River (ELK1)
- RD 0827-Elkhorn - Unit 2, Yolo Bypass (ELK2)
- RD 1600-Mull - Unit 1, Sacramento River (MUL1)
- RD 1600-Mull - Unit 2, Yolo Bypass (MUL2)
- Sacramento Bypass - Unit 1, north levee (SAC1)
- Yolo Bypass - East Levee (YBEL)

Other Federal Levees

Flood Control Structure

Pump Station

Levee Mile

**FEDERAL LEVEE PROJECTS
SYSTEM MAP**

**RD 1600-MULL, RD 827-ELKHORN,
RD 785-DRIVER, AND RD 537-LOVDAL**

**U.S. ARMY CORPS OF ENGINEERS
SACRAMENTO DISTRICT**

RD 1600, 827, 785, and 537- Sac Yolo North

		System: RD 1600, 0827, 0785, and 0537 - SacYolo North Levee System System Rating: Unacceptable Approved SWIF / LOI: No PL 84-99 RP Eligibility: Inactive		<div>RD 0537 - Lovdal - Unit 1, Sacramento River north of Sac Bypass (LOWN)</div> <div>RD 0785 - Driver - Unit 1, Sacramento (DRV1)</div> <div>RD 0785 - Unit 2, Yolo Bypass (DRV2)</div> <div>RD 0827 - Elkhorn - Unit 1, Sacramento River (ELK1)</div> <div>RD 0827 - Elkhorn - Unit 2, Yolo Bypass (ELK2)</div> <div>RD 1600 - Mull - Unit 1, Sacramento River (MUL1)</div> <div>RD 1600 - Mull - Unit 2, Yolo Bypass (MUL2)</div> <div>Sacramento Bypass - Unit 1, North Levee (SAC1)</div> <div>Yolo Bypass - East Levee (YBEL)</div>							
General	Operations and Maintenance Manuals	A	A	A	A	A	A	A	A	A	
	Emergency Supplies and Equipment	M	M	M	M	M	M	M	A	A	
	Flood Preparedness and Training	M	M	M	M	M	M	M	M	M	
Levee - Items Affecting PL 84-99 RP Eligibility	Encroachments	U	U	M	M	U	U	U	U	M	
	Closure Structures	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
	Slope Stability	U	M	U	M	U	M	U	M	A	
	Erosion/Bank Caving	U	U	U	M	M	U	U	M	A	
	Animal Control	U	U	U	U	U	U	U	M	U	
	Culverts/Discharge Pipes	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
	Underseepage Relief Wells/Toe Drainage Systems	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
Levee Embankments - Other Items	Vegetation Growth	M	M	M	M	M	M	M	M	M	
	Sod Cover	U	M	M	M	M	U	M	M	M	
	Settlement	A	A	M	A	M	M	M	M	M	
	Depressions/Rutting	M	U	M	M	M	M	M	M	A	
	Cracking	A	A	U	A	U	A	U	M	A	
	Riprap Revetments & Bank Protection	M	U	U	M	M	M	M	M	M	
	Revetments other than Riprap	M	N/A	N/A	N/A	N/A	N/A	N/A	M	N/A	
	Seepage	A	M	M	M	M	U	M	M	M	
<div><div><div>Legend</div><div>A Acceptable</div><div>M Minimally Acceptable</div><div>U Unacceptable</div><div>N/A Not Applicable</div><div>RP Rehabilitation Program (Note: flood fight assistance available regardless of eligibility status)</div></div><div><div>M</div><div>Includes Unacceptable observations not likely to prevent performance in next flood event</div></div><div><div>U</div><div>Serious deficiency noted in past inspection report has not been corrected</div></div><div><div>U</div><div>Likely prevents performance in next flood event</div></div></div>											



