

# CVFPB MEETING - August 22, 2014




## AGENDA ITEM 7-C

### Informational Briefing

### Unacceptable DWR Levee Inspection Ratings

Re



**MBK**  
ENGINEERS

1771 Tibbuz Road, Suite A  
Sacramento, California 95815  
Phone: (916) 436-4400 • Fax: (916) 436-0253

RECLAMATION DISTRICT NO. 999  
NETHERLANDS DISTRICT

**AERIAL MAP  
WITH STATIONING**

SCALE:	1" = 10,000'
JOB NUMBER:	4163
DRAWN BY:	AR
DATE:	02/06/2013
SHEET:	1 OF 1

# Reclamation District 999



Intentional rut  
By landowner  
to prevent access



# Reclamation District 999



Evidence of  
Illegal access



# Reclamation District 999



Rutting  
corrected



# Reclamation District 999



Rutting  
corrected



# Reclamation District 999



Rutting on  
Yolo County  
Road 107



# Reclamation District 999



Large distance  
from levee crown  
to water



# Reclamation District 999



Solano County,  
Holland Road

